

IMMEDIATE ACTION

SERVICE



BULLETIN

NUMBER 118


September 21, 1951

SUBJECT: Battery Box Lid Modification

MODELS AFFECTED: PA-16 Airplanes with Serial Numbers 16-1 and up;
PA-20 Airplanes with Serial Numbers 20-1 thru
20-802 inclusive; and PA-22 Airplanes with Serial
Numbers 22-1 thru 22-348 inclusive.

It is necessary that the battery box lids in the above listed airplanes be modified in accordance with the following instructions, to eliminate the possibility of "shorting" the battery terminal wing nuts.

Remove the wood block located between the battery cable openings. Place the fibre insulator, Piper Part Number 90150-8, inside the lid as shown in the following sketch. Replace the wood block using the same screws.



End.

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.