

FIGURE Z-22. FIX FOR "RUN-ON" IN STARTERS WITH PERMANENT MAGNET MOTORS.

REV -K- 02/20/05

