

| | | | | | | |
|----------|----|-------|-------|-------|------------|--------------|
| 590 | 12 | 0.50 | 0.200 | 5000 | T-1 1/4 | 9.09 |
| 7153 | 13 | 5.00 | 0.115 | 40000 | T-3/4 | 13.64 |
| 6833 | 13 | 5.00 | 0.060 | 25000 | T-3/4 | 13.18 |
| 7153AS15 | 13 | 5.00 | 0.115 | 40000 | T-3/4 | 15.50 |
| 7219 | 13 | 12.00 | 0.060 | 10000 | T-1 | 3.86 |
| 715AS15 | 13 | 5.00 | 0.115 | 40000 | T-1 | 12.02 |
| 7152 | 13 | 5.00 | 0.115 | 40000 | T-1 | 11.14 |
| 715 | 13 | 5.00 | 0.115 | 40000 | T-1 | 11.73 |
| 680 | 13 | 5.00 | 0.060 | 60000 | T-1 | 10.00 |
| 6838 | 13 | 28.00 | 0.024 | 4000 | T-1 | 16.59 |
| 6832 | 13 | 5.00 | 0.060 | 25000 | T-1(Short) | 1.23 |
| 713 | 13 | 5.00 | 0.075 | 25000 | T-1 | 3.64 |
| 7009 | 13 | 28.00 | 0.024 | 1500 | T-1(Short) | 2.27 |
| 7218 | 13 | 10.00 | 0.027 | 10000 | T-1 | .43 |
| 685* | 14 | 5.00 | 0.060 | 25000 | T-1 | 1.59 |
| 682* | 14 | 5.00 | 0.060 | 60000 | T-1 | 1.75 |
| 6839 | 14 | 28.00 | 0.024 | 4000 | T-1 | 17.05 |
| 718 | 14 | 5.00 | 0.115 | 40000 | T-1 | 18.41 |
| 6180 | 14 | 5.00 | 0.060 | 5000 | T-1 | 1.21 |
| 7241 | 14 | 18.00 | 0.026 | 10000 | T-1 | .83 |
| 7839 | 15 | 28.00 | 0.024 | 4000 | T-1 | 18.64 |
| 7680 | 15 | 5.00 | 0.060 | 60000 | T-1 | 17.27 |
| 7683 | 15 | 5.00 | 0.060 | 25000 | T-1 | 20.00 |
| 7265* | 15 | 5.00 | 0.060 | 5000 | T-1 | .75 |
| 7715 | 15 | 5.00 | 0.115 | 40000 | T-1 | 16.59 |
| 7328 | 15 | 6.00 | 0.200 | 1000 | T-1 3/4 | 10.91 |
| 7387 | 15 | 28.00 | 0.040 | 7000 | T-1 3/4 | 8.64 |
| 7361 | 15 | 5.00 | 0.060 | 25000 | T-1 3/4 | 8.86 |
| 7374 | 15 | 28.00 | 0.040 | 10000 | T-1 3/4 | 11.14 |
| 7373 | 15 | 14.00 | 0.100 | 10000 | T-1 3/4 | 9.77 |
| 7371 | 15 | 12.00 | 0.040 | 10000 | T-1 3/4 | 10.00 |
| 7382 | 15 | 14.00 | 0.080 | 15000 | T-1 3/4 | 10.00 |
| 7327 | 15 | 28.00 | 0.040 | 4000 | T-1 3/4 | 10.91 |
| 7349 | 15 | 6.30 | 0.200 | 5000 | T-1 3/4 | 6.82 |
| 7366 | 15 | 5.00 | 0.200 | 15000 | T-1 3/4 | 2.84 |
| 7376 | 15 | 28.00 | 0.065 | 5000 | T-1 3/4 | 1.25 |
| 7632 | 15 | 28.00 | 0.040 | 1000 | T-1 1/4 | 20.23 |
| 7646 | 15 | 14.00 | 0.080 | 1000 | T-1 1/4 | 21.36 |
| 7876 | 15 | 28.00 | 0.060 | 25000 | T-1 3/4 | 6.82 |
| 7381 | 15 | 6.30 | 0.200 | 20000 | T-1 3/4 | 6.82 |
| 1255P | 16 | 12.00 | 0.040 | 7500 | T-2 | 11.26 |